



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070007		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, November 08, 2006		
Start Date/Time:	11/8/2006 8:00:00 AM		
End Date/Time:	11/8/2006 3:00:00 PM		
Last Inspection:	Wednesday, September 07, 2005		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 47 Deg. F. InspectionID Report Number: 1126

Types of Operations

Accepted by: whedberg 12/5/2006

Permitee: SUNNYSIDE COAL CO Operator: SUNNYSIDE COAL CO

Site: SUNNYSIDE MINE Address: 99 W MAIN # 202, LEHI UT 84043

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: FORFEITURE

Current Acreages

Total Permitted	287.40	
Total Disturbed	287.40	
Phase I		
Phase II		
Phase III	28.00	

Mineral Ownership

✓ Federal Underground State ☐ Surface **✓** County ☐ Loadout **✓** Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date Wednesday, November 08, 2006

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070007 Inspection Type: COMPLETE

Inspection Date: Wednesday, November 08, 2006

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring		✓		
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓	✓		
	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	✓	✓		
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V	✓		
11.	Contemporaneous Reclamation	V	✓		
12.	Backfilling And Grading	✓	✓		
13.	Revegetation	V		V	
14.	Subsidence Control	V	V		
15.	Cessation of Operations	V	V		
16.a	Roads: Construction, Maintenance, Surfacing	V		✓	
16.Ł	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓	V		
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V	V		
20.	Air Quality Permit	V	V		
21.	Bonding and Insurance	V	V		
22.	Other				

Permit Number: C0070007 Inspection Type: COMPLETE

Inspection Date: Wednesday, November 08, 2006

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The site was reclaimed as of July1, 1999. On January 9, 200,1 the Division determined that the site met the criteria for an "Abandoned Site" in accordance with R645-400. The site remains as a bond forfeiture site.

2. Signs and Markers

Remnant ID signs and markers remain through out the site.

3. Topsoil

The soils used for reclamation of the mine site continues to support the vegetation at the main facilities area and in the reclaimed remote areas.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The surface facilities pond is still in place and still contains a primary and emergency spillway. All other sediment ponds and mine water ponds have been reclaimed or were transferred to the Sunnyside Cogeneration permit C/007/035.

13. Revegetation

The vegetation cover on the reclaimed areas appears to be successful with abundant growth and species diversity.

16.a Roads: Construction, Maintenance, Surfacing

Access roads to the main facilities, fan and water canyon area are gated and locked. Several roads have become impassable by a vehicle, because of erosion.